

REPLACEMENT OUTBOARD STARTERS



The Leader in Marine Electrical Parts.



TECH TIP

- Excess oil or grease may cause drive failure.
- Be sure to follow the lubrication directions shown on page 17.

NOTE

When ordering drive assemblies for B.R.P./O.M.C. starters, be aware that some B.R.P./O.M.C. outboard starters use a 2-piece drive assembly; older B.R.P./O.M.C. starters use a 1-piece drive assembly.

**ORDER THE
CORRECT DRIVE.**

**THEY ARE NOT
INTERCHANGEABLE!**

5362 (NEW)

FITS: MERCURY 40-50 HP
1997-UP 4-Stroke
9-tooth metric drive gear



DV362
9-tooth metric
drive gear



SR362
Brush holder assembly



5363 (NEW)

FITS: O.M.C.
1991-UP 150-175 HP
V6 Eagle-Series
1997-UP V4 and V6
2003 75/90/115 HP
2003-UP 90/105/115
60° Engine
2004-UP 100-175 HP
Direct Injection



DV517
9-tooth
drive gear



DV518
10-tooth
drive gear



SR363
Brush holder assembly

JSA517

Jack shaft assembly/9-tooth drive gear
Fits Johnson Evinrude carbureted engines



JSA518

Jack shaft assembly/10-tooth drive gear
Fits Johnson Evinrude direct injection engines



5364 (NEW)

FITS: MERCURY
1998-UP 25 HP, 4 Stroke
Yamaha 25HP, 4 Stroke
9-tooth drive gear



DV364
9-tooth
drive gear



SR364
Brush holder assembly



5365 (NEW)

FITS: MERCURY
30/40/50/60 HP
1999-UP 3-cyl, 4 Stroke
2000-UP Yamaha
40HP, 4 Stroke
9-tooth drive gear



DV365
9-tooth
drive gear



SR365
Brush holder assembly



5366 (NEW)

FITS: MERCURY
35-50 HP
9-tooth drive gear



DV366
9-tooth
drive gear



SR366
Brush holder assembly





The Leader in Marine Electrical Parts.

REPLACEMENT OUTBOARD STARTERS



TECH TIP

- Excess oil or grease may cause drive failure.
- Be sure to follow the lubrication directions shown on page 17.

NOTE

When ordering drive assemblies for B.R.P./O.M.C. starters, be aware that some B.R.P./O.M.C. outboard starters use a 2-piece drive assembly; older B.R.P./O.M.C. starters use a 1-piece drive assembly.

ORDER THE CORRECT DRIVE. THEY ARE NOT INTERCHANGEABLE!

5368 (NEW)

FITS: O.M.C.
 1997-2000
 9.9/15 HP, 4-stroke
 10-tooth drive gear



DVK68*
 2-pc drive kit
 *See NOTE

SR368
 Brush holder assembly

5367 (NEW)

FITS: MERCURY/MARINER
 1986-1996 6-15 HP
 1980-2003 18-25 HP
 10-tooth drive gear
 2½" motor casing



DV367
 10-tooth drive gear



SR367
 Brush holder assembly



5369 (NEW)

FITS: O.M.C.
 8/9.9-11 HP
 1997-1998 4 stroke
 1977-1992 9.9-15 HP
 10-tooth drive gear
 2" motor casing



DV369
 10-tooth drive gear



SR369
 Brush holder assembly



Save Time With ARCO SR107 - BRUSH LOADING TOOL See page 75

Makes brush loading as simple as 1-2-3
 The "perfect tool" for loading outboard starter brushes.
 Strong stainless steel construction.



One Tool Fits All These Caps!

(1) Depress Brushes and Slide End Cap In Tool

(2) Insert Armature

(3) Remove Tool Leaving Brushes Loaded For Assembly



© ARCO STARTING & CHARGING SPECIALISTS

Toll Free 800-722-2720 • Phone 850-455-5476 • Fax 850-453-2630 • www.arcomarine.com

REPLACEMENT OUTBOARD STARTERS



The Leader in Marine Electrical Parts.



TECH TIP

- Excess oil or grease may cause drive failure.
- Be sure to follow the lubrication directions shown on page 17.

NOTE

When ordering drive assemblies for B.R.P./O.M.C. starters, be aware that some B.R.P./O.M.C. outboard starters use a 2-piece drive assembly; older B.R.P./O.M.C. starters use a 1-piece drive assembly.

**ORDER THE
CORRECT DRIVE.**

**THEY ARE NOT
INTERCHANGEABLE!**

5370 (NEW)
FITS: O.M.C.
55-75 HP 3-cyl
9-tooth drive gear



DV370*
9-tooth drive gear
*See NOTE

DVK70*
2-pc drive kit
*See NOTE



SR370
Brush holder assembly

5371 (NEW)
FITS: O.M.C.
50-60 HP 2-cyl
9-tooth drive gear



DV371*
9-tooth drive gear
*See NOTE

DVK71*
2-pc drive kit
*See NOTE



SR371
Brush holder assembly

5372 (NEW)
FITS: O.M.C.
85-140 HP; Late-model V4
Small 10-tooth drive gear



DV372*
Small 10-tooth drive gear
*See NOTE

DVK72*
2-pc drive kit
*See NOTE



SR372
Brush holder assembly

5372X (NEW)
FITS: O.M.C.
1969-1970 85-115 HP
1971-1972 85-125 HP
Large 10-tooth drive gear



DV372X
Large 10-tooth drive gear

SR372
Brush holder assembly

5373 (NEW)
FITS: O.M.C.
150-235 HP V6
8-tooth drive gear



DV373
8-tooth drive gear

SR373
Brush holder assembly





The Leader in Marine Electrical Parts.

REPLACEMENT OUTBOARD STARTERS



TECH TIP

- Excess oil or grease may cause drive failure.
- Be sure to follow the lubrication directions shown on page 17.

NOTE

When ordering drive assemblies for B.R.P./O.M.C. starters, be aware that some B.R.P./O.M.C. outboard starters use a 2-piece drive assembly; older B.R.P./O.M.C. starters use a 1-piece drive assembly.

ORDER THE CORRECT DRIVE.

THEY ARE NOT INTERCHANGEABLE!

5374 (NEW)
FITS: MERCURY
 65-85 HP 4-cyl
 10-tooth drive gear



DV374
 10-tooth drive gear



SR374
 Brush holder assembly



5374X (NEW)
FITS: MERCURY
 1956-1957 25-30 HP
 1957 55 HP
 1958 30-55 HP
 1959 35 & 55 HP
 Large 10-tooth drive gear



DV374X
 Large 10-tooth drive gear



SR374
 Brush holder assembly



5375 (NEW)
FITS: MERCURY/MARINER
 50-90 HP/65 HP Jet
 10-tooth drive gear



DV375
 10-tooth drive gear



SR375
 Brush holder assembly



5376 (NEW)
FITS: O.M.C.
 18-40 HP
 11-tooth drive gear



DV376*
 11-tooth drive gear
 *See NOTE



DVK76*
 2-pc drive gear kit
 *See NOTE



SR376
 Brush holder assembly



5377 (NEW)
FITS: MERCURY/MARINER
 90-175 HP Inline
 150 HP V6
 10-tooth drive gear



DV377
 10-tooth drive gear



SR377
 Brush holder assembly



© ARCO STARTING & CHARGING SPECIALISTS

Toll Free 800-722-2720 • Phone 850-455-5476 • Fax 850-453-2630 • www.arcomarine.com

REPLACEMENT OUTBOARD STARTERS



The Leader in Marine Electrical Parts.



TECH TIP

- Excess oil or grease may cause drive failure.
- Be sure to follow the lubrication directions shown on page 17.

NOTE

When ordering drive assemblies for B.R.P./O.M.C. starters, be aware that some B.R.P./O.M.C. outboard starters use a 2-piece drive assembly; older B.R.P./O.M.C. starters use a 1-piece drive assembly.

**ORDER THE
CORRECT DRIVE.
THEY ARE NOT
INTERCHANGEABLE!**

5378X (NEW)

FITS: MERCURY/MARINER
V150 HP, V175 HP
Large 10-tooth
drive gear



DV378X
Large
10-tooth
drive gear



SR380

Brush holder assembly



5380 (NEW)

FITS: MERCURY/MARINER
135-200 HP V6
105 HP Jet
8-tooth drive gear



DV380
8-tooth
drive gear



SR380

Brush holder assembly



5381 (NEW)

FITS: MERCURY
1999-UP 2.5 DFI
1996-1999 200 HP V6 DFI
1998-Up 225 HP V6 DFI
1999-Up 3.0L V6
9-tooth drive gear



DV381
9-tooth
drive gear



SR381

Brush holder assembly



5379 (NEW)

FITS: MERCURY/MARINER
40-50 HP
10-tooth drive gear



DV379
10-tooth
drive gear



SR379

Brush holder assembly



5381X (NEW)

FITS: MERCURY/MARINER
150-225 HP
9-tooth drive gear



DV381
9-tooth
drive gear



SR380

Brush holder assembly





The Leader in Marine Electrical Parts.

REPLACEMENT OUTBOARD STARTERS



TECH TIP

- Excess oil or grease may cause drive failure.
- Be sure to follow the lubrication directions shown on page 17.



NOTE

When ordering drive assemblies for B.R.P./O.M.C. starters, be aware that some B.R.P./O.M.C. outboard starters use a 2-piece drive assembly; older B.R.P./O.M.C. starters use a 1-piece drive assembly.

ORDER THE CORRECT DRIVE.

THEY ARE NOT INTERCHANGEABLE!

5382 (NEW)
FITS: CHRYSLER/FORCE
 35-50 HP
 11-tooth drive gear



DV382
 11-tooth drive gear



SR382
 Brush holder assembly



5384 (NEW)
FITS: MERCURY/MARINER
 2.0L, 2.4L, 2.5L V6,
COUNTER-ROTATING,
RACING OUTBOARDS
 10-tooth drive gear



DV384
 10-tooth drive gear



SR384
 Brush holder assembly



5385 (NEW)
FITS: MERCURY
 35-40 HP, 2-cyl
 10-tooth drive gear



DV385
 10-tooth drive gear



SR385
 Brush holder assembly



5386 (NEW)
FITS: O.M.C.
 1985-Up
 120-140 HP V4
 10-tooth drive gear



DV386*
 10-tooth drive gear
 *See NOTE

DVK86*
 2-pc drive kit
 *See NOTE



SR386
 Brush holder assembly



5387 (NEW)
FITS: O.M.C.
 V6, V8 loop
 10-tooth drive gear



DV387
 10-tooth drive gear



SR387
 Brush holder assembly



© ARCO STARTING & CHARGING SPECIALISTS

Toll Free 800-722-2720 • Phone 850-455-5476 • Fax 850-453-2630 • www.arcomarine.com

REPLACEMENT OUTBOARD STARTERS



The Leader in Marine Electrical Parts.



TECH TIP

- Excess oil or grease may cause drive failure.
- Be sure to follow the lubrication directions shown on page 17.

NOTE

When ordering drive assemblies for B.R.P./O.M.C. starters, be aware that some B.R.P./O.M.C. outboard starters use a 2-piece drive assembly; older B.R.P./O.M.C. starters use a 1-piece drive assembly.

**ORDER THE
CORRECT DRIVE.
THEY ARE NOT
INTERCHANGEABLE!**

5388 (NEW)
FITS: MERCURY
50-60 HP, 3-cyl,
1991-1996 45 HP Jet
10-tooth drive gear



DV388
10-tooth
drive gear



SR388
Brush holder assembly



5389 (NEW)
FITS: O.M.C.
1989-Up 25, 40, 50 HP; 2-cyl
1990-Up 48-50 HP
9-tooth drive gear



DV389*
9-tooth drive gear
*See NOTE



DVK89*
2-pc drive kit
*See NOTE



SR389
Brush holder assembly



5390 (NEW)
FITS: O.M.C.
1987-1993 20-35 HP; 2-cyl
9-tooth drive gear



DV390*
9-tooth drive gear
*See NOTE

DVK90*
2-pc drive kit
*See NOTE



SR390
Brush holder assembly

5392 (NEW)
FITS: MERCURY/MARINER
100-125 HP Inline 4-cyl;
80 HP Jet
8-tooth drive gear



DV392
8-tooth
drive gear



SR392
Brush holder assembly



5393 (NEW)
FITS: CHRYSLER/FORCE
70-150 HP
9-tooth drive gear



DV393
9-tooth
drive gear



SR393
Brush holder assembly





The Leader in Marine Electrical Parts.

REPLACEMENT OUTBOARD STARTERS



TECH TIP

- Excess oil or grease may cause drive failure.
- Be sure to follow the lubrication directions shown on page 17.

NOTE

When ordering drive assemblies for B.R.P./O.M.C. starters, be aware that some B.R.P./O.M.C. outboard starters use a 2-piece drive assembly; older B.R.P./O.M.C. starters use a 1-piece drive assembly.

ORDER THE CORRECT DRIVE.


THEY ARE NOT INTERCHANGEABLE!

5394 (NEW)

Determine location of the battery stud on starter being replaced before ordering - See 5397

FITS: FORCE
1996-1999 40-50 HP
13-tooth drive gear

DV394
13-tooth drive gear



Battery stud exits **BOTTOM** of starter

SR394
Brush holder assembly

5395 (NEW)

FITS: MERCURY/MARINER
1994-Up 225 HP
8-tooth drive gear

DV395
8-tooth drive gear



SR395
Brush holder assembly

5396 (NEW)

FITS: MERCURY
1994-1996 30-40 HP,
2-cyl, 55-60 HP
1997-Up 45 HP Jet
10-tooth drive gear

DV396
10-tooth drive gear




SR396
Brush holder assembly

5397 (NEW)

Determine location of the battery stud on starter being replaced before ordering - See 5394

FITS: FORCE
1992-1995 40 HP
1992-1995 50 HP
13-tooth drive gear

DV397
13-tooth drive gear



Battery stud exits **SIDE** of starter

SR397
Brush holder assembly

5398 (NEW)

FITS: O.M.C.
1997-1999
25-35 HP 3-cyl
10-tooth drive gear

DVK98*
2-pc 10-tooth drive gear
*See Note



SR398
Brush holder assembly



© ARCO STARTING & CHARGING SPECIALISTS

Toll Free 800-722-2720 • Phone 850-455-5476 • Fax 850-453-2630 • www.arcomarine.com

REPLACEMENT OUTBOARD STARTERS



The Leader in Marine Electrical Parts.



TECH TIP

- Excess oil or grease may cause drive failure.
- Be sure to follow the lubrication directions shown on page 17.

NOTE

When ordering drive assemblies for B.R.P./O.M.C. starters, be aware that some B.R.P./O.M.C. outboard starters use a 2-piece drive assembly; older B.R.P./O.M.C. starters use a 1-piece drive assembly.

**ORDER THE
CORRECT DRIVE.**

**THEY ARE NOT
INTERCHANGEABLE!**

5399 (NEW)

**MOTOR ONLY
FITS: O.M.C.**

90-115 HP
1997-UP 60° V4
1998-2000 80 HP
1998-2000 100 HP



**DV517
9-tooth
drive gear**



**SR399
Brush holder assembly**



JSA517

Jack shaft assembly/9-tooth drive gear
Fits Johnson Evinrude carbureted engines



5400 (NEW)

**FITS: MERCURY
2001-UP**

135-250 HP
200-250 Sport Jet
2005-UP

**VERADO 4 STROKE
200-275 HP
14-tooth drive gear**



**SW463
Replacement solenoid**

5551 (NEW)

FITS: CHRYSLER

25-35 HP

Large 10-tooth drive gear



**DV551
Large 10-tooth
drive gear**



SR551

Brush holder assembly



7325 (NEW)

FITS: MERCURY/FORCE

90-120 HP Sport Jet

9-tooth drive gear



**DV325
9-tooth
drive gear**



SR325

Brush holder assembly



7326 (NEW)

FITS: MERCURY

1996-UP V6 Sport Jet

8-tooth drive gear



**DV326
8-tooth
drive gear**



SR326

Brush holder assembly

