

98185 (NEW)

FITS: YANMAR

4JH, QM20,
2QM20, & 2T engines

Replaces: Hitachi S114-483,
S114-815

