

# REPLACEMENT OUTBOARD STARTERS



The Leader in Marine Electrical Parts.



## 3410 (NEW)

**FITS: TOHATSU** 45-140 HP, **2 Stroke**

Replaces: Hitachi S114-415A,  
S114-415, S114-571A,  
S114-667

**9-tooth drive gear**



### DV510\*

**9-tooth  
drive gear**



### SR410\*

**Brush holder  
assembly**



**\*Will Fit These Starters Only:**

**ARCO** 3410, Hitachi S114-667, Tohatsu FM 5900

## 3421 (NEW)

**FITS: YAMAHA**

**1984-1997** 9.9-15 HP

**1988-1998** 25 HP

Replaces: Hitachi S106-07B,  
S106-07E, S106-07F

**10-tooth drive gear**



## 3412 (NEW)

**FITS: SUZUKI, TOHATSU,  
NISSAN** 30-40 HP, **2 Stroke**

Replaces: Hitachi S108-94,  
S108-112, S108-120

**9-tooth drive gear**



### DV512\*

**9-tooth  
drive gear**



### SR412\*

**Brush holder  
assembly**



**\*Will Fit These Starters Only:**

**ARCO** 3412, Hitachi S108-120, Tohatsu 3C8-76010-100

## 3422 (NEW)

**FITS: YAMAHA**

**1984-UP** 70 HP

**1991-UP** 60 HP, **2 Stroke**

Replaces: Hitachi S108-97A

**9-tooth drive gear**



### DV522\*

**9-tooth  
drive gear**



### SR422\*

**Brush holder  
assembly**



**\*Will Fit These Starters Only:**

**ARCO** 3422, Hitachi S108-97A, Yamaha 6H3-81800-11

## 3420 (NEW)

**FITS: YAMAHA** 25-40 HP, **2 Stroke**  
**MARINER** 20-40 HP, **2 Stroke**

Replaces: Hitachi S108-80,  
S108-80A, S108-80B

**11-tooth drive gear**



### DV520\*

**11-tooth  
drive gear**



### SR420\*

**Brush holder  
assembly**



**\*Will Fit These Starters Only:**

**ARCO** 3420, Hitachi S108-80B, Yamaha 689-81800-13

## 3423 (NEW)

**FITS: YAMAHA**

**1987-Up** 30 HP

**1989-Up** 40-50 HP

Replaces: Hitachi S108-87A

**11-tooth drive gear**



### DV523\*

**11-tooth  
drive gear**



### SR423\*

**Brush holder  
assembly**



**\*Will Fit These Starters Only:**

**ARCO** 3423, Hitachi S108-87A, Yamaha 6F5-81800-11

**3424 (NEW)**

**FITS: YAMAHA, MARINER**  
55-60 HP 2-Cyl, 2 Stroke Engines  
Replaces: Hitachi S114-221  
**9-tooth drive gear**



**DV524\***  
9-tooth  
drive gear



**SR424\***  
Brush holder  
assembly



**\*Will Fit These Starters Only:**  
 3424, Hitachi S114-221J, Yamaha 697-81800-13

**3427 (NEW)**

**FITS: YAMAHA**  
1994-1999 75 HP;  
1991-1996 85 HP;  
1984-UP 90 HP  
Replaces: Hitachi S114-263B,  
**9-tooth drive gear**



**DV527\***  
9-tooth  
drive gear



**SR427\***  
Brush holder  
assembly



**\*Will Fit These Starters Only:**  
 3427, Hitachi S114-263B, Yamaha 688-81800-12

**3425 (NEW)**

**FITS: YAMAHA**  
1984-1988 40-50 HP  
Replaces: Hitachi S108-99B  
**9-tooth drive gear**



**DV525\***  
9-tooth  
drive gear



**SR425\***  
Brush holder  
assembly



**\*Will Fit These Starters Only:**  
 3425, Hitachi S108-99B, Yamaha 6H4-81800-12

**3428 (NEW)**

**FITS: YAMAHA** 115-2.  
Replaces: Hitachi S11  
**9-tooth drive gear**



**DV528\***  
9-tooth  
drive gear



**SR428\***  
Brush holder  
assembly



**\*Will Fit These Starters Only:**  
 3428, Hitachi S114-660B, Yamaha 6N7-81800-10

**3426 (NEW)**

**FITS: YAMAHA**  
1984-1996 115-200 HP, 2 Stroke  
1995-2000 40-50 HP, 4 Stroke  
Replaces: Hitachi S114-323  
**9-tooth drive gear**




**DV526\***  
9-tooth  
drive gear



**SR426\***  
Brush holder  
assembly



**\*Will Fit These Starters Only:**  
 3426, Hitachi S114-323C, Yamaha 6E5-81800-12

**3429 (NEW)**

**FITS: YAMAHA**  
1998-UP V200;  
1994-UP 225 HP  
1990-UP 250 HP  
Replaces: Hitachi S114-559B  
**9-tooth drive gear**



**DV529\***  
9-tooth  
drive gear



**SR429\***  
Brush holder  
assembly



**\*Will Fit These Starters Only:**  
 3429, Hitachi S114-559B, Yamaha 61A-81800-01



# REPLACEMENT OUTBOARD STARTERS



The Leader in Marine Electrical Parts.



## 3430 (NEW)

**FITS: YAMAHA**  
**1999-Up 80 HP, 4 Stroke**  
**1999-Up 100 HP, 4 Stroke**  
**MERCURY/MARINER**  
**90 HP, 4 Stroke**  
 Replaces: Hitachi S114-828B  
**13-tooth drive gear**



## 3440 (NEW)

**FITS: SUZUKI 75/85 HP,**  
**1988-2000 2 Stroke**  
 Replaces: Hitachi S114-555  
**9-tooth drive gear**



**DV540\***  
**9-tooth**  
**drive gear**



**SR440\***  
**Brush holder**  
**assembly**



**\*Will Fit These Starters Only:**

**ARCO** 3440, Hitachi S114-555, Suzuki 31100-95601

## 3431 (NEW)

**FITS: YAMAHA**  
**2000-Up LZ 150-175 HP**  
**2000-Up VZ 150-175 HP**  
**2000-Up Z 150-175 HP**  
**2000-Up LZ 200-2200 HP**  
 Replaces: Hitachi S114-836A  
**13-tooth drive gear**



## 3442 (NEW)

**FITS: SUZUKI 90/100,**  
**150-225 HP, 2 Stroke**  
 Replaces: Hitachi  
 S114-551, S114-674  
**8-tooth drive gear**



**DV542\***  
**8-tooth**  
**drive gear**



**SR442\***  
**Brush holder**  
**assembly**



**\*Will Fit These Starters Only:**

**ARCO** 3442, Hitachi S114-674, Suzuki 31100-92E00

## 3432 (NEW)

**FITS: YAMAHA**  
**2000-Up F115, 4 Stroke**  
**2000-Up LF115, 4 Stroke**  
 Replaces: Hitachi S114-838A  
**13-tooth drive gear**



## 3444 (NEW)

**FITS: SUZUKI**  
**115-140 HP, 2 Stroke**  
 Replaces: Hitachi  
 S114-437, S114-673  
**9-tooth drive gear**



**DV544\***  
**9-tooth**  
**drive gear**



**SR444\***  
**Brush holder**  
**assembly**



**\*Will Fit These Starters Only:**

**ARCO** 3444, Hitachi S114-673, Suzuki 31100-94610

## 3433 (NEW)

**FITS: YAMAHA**  
**2004-Up 150 HP, 4 Stroke**  
**2005-Up 250 HP, 4 Stroke**  
**2006-Up 225 HP, 4 Stroke**  
 Replaces: Hitachi S114-867  
**13-tooth drive gear**





The Leader in Marine Electrical Parts.

# REPLACEMENT OUTBOARD STARTERS



## TECH TIP

- Excess oil or grease may cause drive failure.
- Be sure to follow the lubrication directions shown below.



### “DO NOT”

**SPRAY OIL OR OTHER LUBRICANTS ON O/B STARTER DRIVES**

The O/B Starter Drives are Rubber Cushioned Drives. If any oil gets between the compression nut and the rubber grip surface, drive failure will result.



### “DO”

**REMOVE THE DRIVE ASSEMBLY WHEN APPLYING LUBE TO THE SHAFT**

Always remove the drive assembly before applying lube to the shaft. Only apply a thin film of water resistant grease to the shaft. Make sure to wipe off any excess.

## 3446 (NEW)

**FITS: HONDA**

40 HP, 4 Stroke

Replaces: Hitachi S114-677,

S114-561;

Honda 31200-ZV5-0130,

31200-ZV6A-0130

**9-tooth drive gear**

**CW Rotation**



### SR446\*

**Brush holder assembly**

**\*Will Fit These Starters Only:**

ARCO 3446, Hitachi S114-677, Honda 31200-ZV6A-0130

## 5359 (NEW)

**FITS: MERCURY/MARINER**

8, 9.9, 13.5, 15 HP

**4 Stroke**

**9-tooth drive gear**



### DV359

**9-tooth drive gear**

### SR359

**Brush holder assembly**

## 3447 (NEW)

**FITS: HONDA**

**2002 - UP** 115 & 130 HP

Replaces: Mitsubishi MOT 60381;

Honda: 31200-ZW5-003

**13-tooth drive gear**



## 5360 (NEW)

**FITS: MERCURY**

**2001-UP** 40, 50, 60 HP

**4-cyl, 4 Stroke**

**9-tooth drive gear**



### DV360

**9-tooth drive gear**

### SR360

**Brush holder assembly**

## 5358 (NEW)

**FITS: EVINRUDE**

40, 50, 75, 90 HP

E-Tec Models

**9-tooth drive gear**



### DV358

**9-tooth drive gear**

### SR358

**Brush holder assembly**

## 5361 (NEW)

**FITS: O.M.C.**

**1993-UP** 9.9-15 HP

**Small 10-tooth drive gear**

**2" casing**

### DV361

**Small 10-tooth drive gear**

### SR361

**Brush holder assembly**



© ARCO STARTING & CHARGING SPECIALISTS

Toll Free 800-722-2720 • Phone 850-455-5476 • Fax 850-453-2630 • www.arcomarine.com