

# 3420 (NEW)

**FITS: YAMAHA** 25-40 HP, 2 Stroke

**MARINER** 20-40 HP, 2 Stroke

Replaces: Hitachi S108-80,

S108-80A, S108-80B

11-tooth drive gear



## DV520\*

11-tooth  
drive gear



## SR420\*

Brush holder  
assembly



**\*Will Fit These Starters Only:**



3420, Hitachi S108-80B, Yamaha 689-81800-13